



Sean Haider &lt;sean.a.haider@gmail.com&gt;

---

## cracks in Stealth

---

**Status Graphite** <mail@status-graphite.com>  
To: "Sean A. Haider" <sean.a.haider@gmail.com>

Wed, May 6, 2015 at 7:10 AM

Hi Sean,  
Looks like your bass has either been dropped or got very cold / hot.

The cracks will only be in the lacquer and I don't think there is any structural problem.

Best regards, Rob Green.

---

PLEASE INCLUDE PREVIOUS CORRESPONDENCE IN YOUR REPLY

---

Status Graphite  
6a, Commerce Way  
Whitehall Industrial Estate  
Colchester  
Essex CO2 8HR  
England

Tel : +44 (0)1206 868150  
Fax : +44 (0)1206 868160  
Web : <http://www.status-graphite.com>

E&OE

---

**From:** Sean A. Haider  
**Sent:** Wednesday, April 29, 2015 4:59 AM  
**To:** Graphite Status  
**Subject:** cracks in Stealth

[Quoted text hidden]